



**Photo 1 – Airplane at Rest**



**Photo 2 - Right Wing Post Recovery**





**Photo 3 - Inboard Section of Left Wing Post Recovery**





**Photo 4 - Vertical and Horizontal Post Recovery**





**Photo 5 - Tachometer as Found**





**Photo 6 - Propeller Post Removal from the Engine (Courtesy of Lycoming Engines)**